

DIRECTIONS FOR USE

MOTOMCO MOLE TRAP Trampa De Topos


1 CONTAINS MOLE TRAP

1 LOCATING ACTIVE TUNNELS



- Use a 1/2" dowel or stick to puncture holes in tunnels. Mark holes with lawn flags, or another easy to spot item. Be careful not to crush runway.
- Inspect after 24 hours. Sealed holes indicate mole activity.

3 SETTING THE TRAP



- Position trap so that the indentation made in step 2a is centered between the trap's jaw. Insert jaws into tunnel so that tunnel is perpendicular to trap.*
 - Step straight down on end of yellow foot pedal. Be careful not to cover slot in foot pedal.
 - Work foot pedal down until trigger post comes through slot.
 - Use foot or finger to press trigger post flush with foot pedal. The trap is now set.
- TIP 1:** If trap will not set, check that indentation made in Step 2a is at correct depth;
TIP 2: If trap will not set after several attempts move to a new location and repeat steps 2 & 3.
- * If soil is extremely hard or rocky, use a spade to pre-cut slots for trap jaws.

2 PREPARING TO SET THE TRAP



- Use heel to create 1" indentation for trigger in middle of active tunnel.
- Built in Depth Gauge should fit in indentation to confirm correct depth.

4 MOLE CAPTURE AND REMOVAL



- A raised foot pedal indicates a capture.
- Set trap on bucket and release dead mole by compressing pedal with hands.

5 MOVING & RESETTING MOLE TRAP

If trap has not triggered after 24 to 48 hours, trap may be moved to a new location. Place foot lightly on pedal and use dowel/stick to press the safety release button. Trap will spring upwards when latch is released. Remove trap and move to another active runway, repeating steps 2 and 3 to reset trap.



Available Exclusively From:

MOTOMCO

3699 Kinsman Blvd.
Madison, WI 53704 U.S.A.



MADE IN USA

Not for sale in NC

EPA EST. NO. 12455-WI-1

www.motomco.com

102009